# PON Optical power meter USER'S GUIDE

English

# WARNING

You are cautioned that changes ormodifications not espressly approved in this document could void yout authority to operate this equipment.

To reduce the risk of fire or electric shock, do not expose this apparatus to rain or moisture.

To avoid electrical shock, do not open the cabinet. Referservicing to qualified personnel only.

## NOTE

As the laser isharmful to the eyes, do not attempt to disassemble the cabinet.





Precautions for Use

#### Use batteries

At the same time, can not use different style or different capacitance batteries.

And only charge the rechargeable batteries.

#### Avoiding condensation problems

As much as possible, avoid sudden temperature changes. Do not attempt to use the drive immediately after moving it from a cold to a warm location, to raising the room temperature suddenly, as condensation may form within the drive. If the temperature changes suddenly while using the drive,

Stop using it and take out batteries for at least an hour.

#### Storage

When long time no use, must take out the batteries to avoid destroying the device.


# Standard




Host



Packet



#### Optional



1-ONT (1310nm) connector

2-VFL/OPM connector

3-OLT/Video (1490/1550nm) connector

4-Display screen

5-F/P mode (PASS, WRNG, FAIL) / main menubutton

6-VFL controlling button

7-Up button

8-Threshold selection menu and calibration menu button

9-Reference setting button

10-Down button


11-USB and data communication interface

12-Power and backlight button


13-Unit selection button

14-Data storage / recall button


# Installing the battery



1.Pull the battery cover lock




3.Installing the battery correctly



2.Raise the battry cover




4.Push the battery cover and lock




Press the Power key to turn on the device with autopower off. After 10 minutes no key pressed, it will autopower off. Press Power key for 2 seconds when turn on the device, the auto power off will be cancelled, and the LCD will show " (C), "

Also press it for more than 2 seconds to shut the device.




According to different configuration, OPM or VFLas optional part can bebuilt in the PON meter Without OPM or VFL, it willshow "NO".

After booting, the metershows function selectionmenu. Press Up button or Down button to switch functions. Then press " ( )" button to entercorresponding interface. If you want to select functions again, only need to press " ( )" button for two seconds or more, and you can return to function selectionmenu.



Testing configuration diagram of ONT Port sending optical power averagely


PON optical powermeter



After entering PON power meter function, it will show a testing interface on the screen. PON power meter can measure uplink signal 1310nm, downlink data signal 1490nm and downlink video signal 1550nm in the PON network at the same time.

HI and LOW mean the result is out of the testing range.

PON optical powermeter - quickjudgement



Ouick judgment mode is a comparison between actual measured data and pre-setting threshold. Then device can quickly judge whether the network meets the communication requirement or not . (Threshold setting is described in detail in the chapters followed.) Press " \* button to open or close the alarm function ( PASS, WRNG, FAIL)On LCD there are warning words beside the result And the LED of each wavelength will turn on: RED LED: FAIL ORANGE LED: WRNG


GREEN LED: PASS

PON optical powermeter - reference setting



Setting reference is usually used before measuring the real network. It can wipe off the attenuation value which is not counted in the actual loss. Or it can be used in comparing with the pre-setting standard power.


" Button is used to setting or checking out the reference value. Short pressit, the screen will show "REF" and a pre-setting dBm value. Long press it for two seconds or more, the device will save the current measured value as a new reference value. At the same time, "REF" sign will flash three times on the display screen. After that, it will show the dB value, and three wavelengths will be set simultaneously. PON optical powermeter - threshold and offset (calibration) setting



The threshold isset to quickly detect whether the result is in range or not, and to confirm whether the network can be used or not. The offset value is set to calibrate the regular attenuation or deviation between standard value and measured value

Short press " mutual" " button, it willenter into threshold setting menu. Pressagain, it willenter into calibration menu.

#### PON optical powermeter - threshold setting




After entering threshold settingmenu, the cursorwill default stay on the threshold number. Firstly, youshould choose the threshold number which you need to set ormodify through pressing " button. The device an set 10 groups of thres hold information. Whenstart quick judgment mode, it will show the current referring threshold number on the top of the display screen, in the form of "Tx". When finish choosing threshold number, you can set corresponding parameters through Up button, Down button and " button. Each channel has three parameters. For example, 1310nm includes parameters as followed:

ONU:1310nm OVER FAIL:03.0 dBm LOW WRNG :-20.0 dBm LOW FAIL :-30.0 dBm Wavelengths be set

Upper limit (Over this power can not communicate) Lower limit warning (Close to non-communication) Lower limit (Below this power can not communicate)

When the cursor move to the corresponding parameter, press " ( ) button, it can shift to each data. Press Up button or Down button to modify. Then press " ( ) button until the whole data change to cursor, which means modifying successfully. After finishing setting, press " ( ) button to back to the testing interface.

### PON optical powermeter - offset(calibration) setting



The followings will cause the test result differenct:


- 1.Different standard
- 2.Not use standard accessories. (Lablevel 0 dB adapter, 0 dB

patch cord)

- 3.Dirty of connector
- 4.More than 1 yearno calibration

User can do easycalibration as the followingsteps:


Press the " [ wey to the calibration menu as the picture. 1.Press the " [ wey to move the cursor. 2.Press the " ( ) " key to increase the value 3.Press the " ( ) " key to decrease the value 4.Press again the " ( ) " key to save and exit. Please note the adjustable range of each wavelength is from -5.0 to +5.0, if the difference is out of the range, we suggest users end back to manufacturer to do completely calibration. PON optical powermeter - datastorage



The measured data storage is used to record the important measured data, which can be used to analysis after measuring. Under measurement interface, press " ( )" button can display the saved historical data. Press Up or Down button can browse records and show the data number on the top of the screen. Press this button for two seconds under current interface, the number will be showed on the upper left of the screen and store the current measured data (by dBm value). The device can store 100 records at most. The data number will plus 1 automatically. If stores fully, the device will overwrite the first record automatically. Successively store data as above-mentioned.

Press "

PON optical power meter- display unit



The measured data will be display in dBm value and uW

value. Press " and a button can switch display unit.

#### Optical power meter



Optical power meter mode is a superior optical power meter with storage function. The dBm value and uW value show simultaneously, operations as followed:

Treeshold Press to witch the measured wavelengths, calibration

wavelengths are: 850/1300/1310/1490/1550/1625nm

REF/ Enter Short press can check the saved references of six

calibration wavelengths above-mentioned. Long press

this button can save current value as a reference.

Device can store 100 records. Short press can check 10 records and press Up or Down button can turn pages. Long press can save current data to device. The data number will plus 1 automatically. Ifstores fully, the device will overwrite the first record automatically. Successively store data as above-mentioned. VFL



Visual FaultLocator(VFL) is used to seek the failure point in bare fiber and cables, including rupture, lager loss, connector seeking and so on. Press "vr." button, the laserwill flash or keep on bright. You can use VFL both in PON power meter mode and optical power meter mode. Press "vr." button can control laser open, close and flash, which will be showed on the screen by "\*" symbol.

# Batteries detecting and charging

Four levels indication of power detection

Represents the remaining 80%----100% electricity

Represents the remaining 40%----80% electricity

Represents the remaining 20%----40% electricity

Represents the remaining electricity less than 20%
After connecting the USB charger, a charging icon showson the
screen. If there are rechargeable batteries in the device, it starts

chargingthe rechargeable batteries. Forbid using non-rechargeable batteries to charge, or it might lead to leakage, even burning.

When the remaining electricity is less than 20%, you should promptly shut down the device and recharge it. Long time undervoltage will shorten the lifetime of the rechargeable batteries. When the charging is finished, the battery remaining indicator will stop flashing. The batteries has finished the fast recharge and can be used directly If you do not stop recharging at this time, the device will continue the trickle charge state, using small current to supply natural discharge. But this processis not more than 24 hours. The device can still be used while charging.

# Detail parameters

1310nm Uplink test		
Spectrum passband	1260nm~1360nm	
Measurement range	-40dBm~+10dBm	
Max. permitted input level	15dBm	
Isolation (for 1490/1550nm)	>40dB	
Accurate Of Burst Signal	Deviation $< \pm 0.5$ dB@-10dBm	
1490nmDownlink test		
Spectrum passband	1480nm~1500nm	
Measurement range	-50dBm~+10dBm	
Max. permitted input level	15dBm	
Isolation (for 1310nm)	>40dB	
Isolation (for 1550nm)	>40dB	
1550nmDownlink test		
Spectrum passband	1530nm~1570nm	
Measurement range	-50dBm~+25dBm	
Max. permitted input level	25dBm	
Isolation (for 1310nm)	>40dB	
Isolation (for 1490nm)	>40dB	
Optical fiber type	SM 9/125um	
Optical fiber connector	SC/PC or customized	
Accurate	$\pm$ 0.2dB/ $\pm$ 0.5dB(burst mode	
Linearity	0.1dB	
Inserting loss	<1.5dB	
Applicable batteries	AA x 3 or AC/DC adapter	
Battery lifetime	>20H	
Charging function	Included	
Auto power off	Included	
Operation temperature	-10~+60°C	
Storage temperature	-20~+70°C	
Relative humidity	<95%No condensation	
Weight	270g	
Size	38mm*98mm*168mm	

# Detail parameters

VFL part		
velength	650nm	
wer		
	1 mW	
	10mW	
	15mW	
	20mW	
	25mW	
	30mW	
er adapter	2.5mmUPP	
Measurement range		
ent range		
	-70dBm~+8dBm	
	-60dBm~+18dBm	
	-50dBm~+26dBm	
	0.01dB	
	$\pm$ 0.2dB	
	±2%	
/pe	InGaAs	
er adapter	FC/Universal connector	
h response range	700~1700nm	
n wavelength	850/1300/1310/1490/1550/1625nm	
Selection guide		
Standard PON Optical powermeter		
$Standard \ PON \ Optical \ power meter + Optical \ power \ meter (-70 \sim +8dBm)$		
Standard PON Optical powermeter+Optical power meter[-60~+18dBm]		
Standard PON Optical powermeter+Optical power meter[-50~+26dBm]		
Standard PON Optical powermeter + 1mW VFL		
Standard PON Optical powermeter+10mW VFL		
7 Standard PON Optical powermeter+15mW VFL		
Option 8 Standard PON Optical powermeter+20mW VFL		
Option 9 Standard PON Optical powermeter+25mW VFL		
Option 10 Standard PON Optical powermeter+30mW VFL		
	er adapter ent range ent range ent range ent range ent range er adapter h response range wavelength Standard PON Optic Standard PON Optic	